



Crimping JPT terminals with TOL-001




1. Get parts ready and strip wire




2. Twist wire and add seal




3. Bend copper wire




4. Position terminal around seal



5. Use Pliers to bend long legs of terminal lightly into place




6. So it looks like this before the crimp tool in used




7. Position assembly into crimp tool




8. Another view of assembly in crimp tool



9. A view of assembly in the crimp tool from the other side.



10. Support assembly firmly with other hand while squeezing the crimp tool.



11. The finished crimped assembly should look like this.